



Resistance Table for Pressure Sender

PSI (100)	0	10	20	30	40	50	60	70	80	90	100
R(Ohm)	240	205	171	143	123	103	88	74	60	47	33
V (mV)	2.40V	2.05V	1.71V	1.43V	1.23V	1.03V	(880)	(740)	(600)	(470)	(330)